

Medusa Series

Product User Manual

Thermal Imaging Camera



RA6-50LRF

CONTENTS

Т

1. Product Overview	01
2. Product Components	02
3. Package Contents	03
4. Operation Instructions	03
5. Button Functions	04
6. Menu Functions	05
7. APP Connection	07
8. Technical Specifications	08
9. Maintenance and Care	11



1. Product Overview

1. The RA6-50LRF is an infrared thermal imaging Device designed for observation and ranging in nighttime and adverse weather conditions.

2. The infrared optical system captures the infrared radiation emitted by the target. The spectral filter reflects the distribution of the target's infrared radiation energy onto the photosensitive elements of the infrared detector array on the focal plane. The detector converts the infrared radiation into electrical signals, which are then amplified and processed by the readout circuit.

3. The core component digitizes the detector's output signals and performs initial infrared image correction, bad pixel elimination, brightness and contrast control, pseudo-color rendering, and overlay of interfaces and crosshairs. The processed signals are sent to the OLED display. The operator observes the infrared thermal imaging of the target through the 14X eyepiece.

2. Product Components



1. Objective Lens Cap	2. Objective Lens	3. Photo/Video Recording Button
4. Menu Button	5. Battery Compartment Cover	6. Eyepiece Eyecup
7. Device Indicator	8. Rangefinder Module	9. Lens Focusing Ring
10. Up Navigation Button	11. Down Navigation Button	12. Data Compartment Cover
13. Power Button	14. Eyepiece Focus Ring	14. Eyepiece Lens

3. Package Contents

RA6-50LRF Thermal Imaging Device
 Carrying Case
 Type-C Data Cable
 User Manual

5V/2A Adapter
Mount (with screws, hex nuts, and wrench)

4. Operation Instructions

4.1. Warnings

(1) Do not point the thermal imaging Device directly at high-intensity radiation sources such as the sun, CO_2 lasers, or welding machines.

(2) The interval between power cycles should be at least 20 seconds.

(3) The thermal imaging Device combines precision optical instruments and electrostatic-sensitive electronic components. Avoid dropping, striking, or vibrating the device to prevent structural deformation or misalignment.

(4) Do not disassemble the thermal imaging Device. Contact the manufacturer for any malfunctions to avoid voiding the warranty.

(5) Remove the battery when not in use or during transportation, and store the device in a protective case.

(6) Replace the battery promptly when it is low to avoid damage from over-discharge.

(7) Using the device outside the specified environmental conditions may cause damage.

4.2. Notes

(1) Clean non-optical surfaces with a clean, soft, dry cloth. Avoid chemical solvents or thinners.

(2) The infrared lens is coated with an anti-reflective film. Clean only when visibly dirty, using a dedicated lens cloth. Avoid touching the lens surface, as fingerprints can damage the coating.

(3) Power off the device when not in use to extend its operational life.

5. Button Functions



(b) Power Button:

(1) Press and hold for 3 seconds to power on/off.

(2) Press and hold for 1-3 seconds to enter sleep mode. Short press to wake from sleep mode.

(3) Short press to refresh in observation mode.

🙆 Photo/Video Button

(1) Short press to take a photo.

(2) Press and hold for 1.5 seconds to start/stop video recording.

🖄 Up Navigation Button:

Short press to navigate up or switch display modes.
 Press and hold to enable/disable picture-in-picture.

Denu Button:

- (1) Short press to access the menu. Use navigation buttons to move through options.
- (2) Press and hold to return to the previous menu level.
- (3) Short press to lock/unlock rangefinder values when LRF is on.

🕖 Down Navigation Button:

(1) Short press to navigate down or switch magnification (1x, 2x, 4x, 8x).

(2) Press and hold to enable/disable rangefinder.

6. Menu Functions

lcon	Main Menu	Description	
		White Hot, High Contrast, Black Hot, Low Light, Fusion. Default: White Hot.	
88	Operation Modes	Image: White Hot High Contrast Black Hot Low Light Fusion	
ŢŲ	Video Output	Enable/Disable CVBS video output.	
(ŀ:	WiFi	Turn on the WiFi function in the device menu, then enable WiFi on your smartphone and open the dedicated app. Locate the device's WiFi MAC address (e.g., "***") and connect by entering the password "12345678". Once the device and smartphone are connected via WiFi, you can observe real-time images captured by the device.	
	Picture-in-Picture	On/Off.	
+	Reticle Type	Options: OFF, 10 types available.	
Φ	Reticle Color	Options: Black, White, Gray, Red, Green.	
	Reticle Profiles	Save user-defined ballistic zeroing parameters.	
¢	Reticle Zeroing Adjustment	Short press the menu button to freeze the image. Briefly press the REC button to move to the X and Y axis values, and use the up and down buttons to adjust the reticle position until it aligns with the impact point. Short press the REC button to move to other options. Once the settings are complete, navigate to the save option and briefly press the menu button to save and exit. Press and hold the menu button to exit without saving. The set distance will be saved as the zeroing point name in the zeroing storage menu.	
Ø	Gyroscope	On/Off.	
	Rangefinder Unit	Meters/Yards.	
6	Rangefinder Settings	On/Off, Set timeout (5, 10, 20 minutes).	
-jąj	Screen Brightness	Adjust brightness (10 levels).	
☆	Brightness	Press the menu button to access the contrast menu, which offers 10 options. Selecting any option will adjust the imaging brightness accordingly.	

	Contrast	Adjust contrast (10 levels).
	lmage Detail Enhancement	Press the menu button to access the image detail enhancement option. The higher the value, the more details are enhanced.
Ŀ	Date/Time	Select the "Date/Time" menu, briefly press the menu button to enter sub-options, use the menu button to navigate, and the up/down buttons to adjust values. Press and hold the menu button to save and exit after adjustments.
۲	Language Settings	Press the menu button to access the language settings menu. Use the up/down buttons to select the desired language, then briefly press the menu button to confirm.
Ŷ	Audio Recording	Select "Audio Recording" and press the menu button to open the sub-menu. Select "On" or "Off" to enable or disable audio recording during video capture.
	Format	Enter the format sub-menu, briefly press the menu button to select "Confirm" or "Cancel". Please proceed with caution! Data cannot be recovered after deletion!
٢	Auto Power Off	Options: 3 minutes, 5 minutes, Off (default). After powering on, you can choose 3 or 5 minutes for auto power-off.
G	Default Settings	Select "Default Settings" and press the menu button to open the sub-menu. Select "Confirm" or "Cancel" to restore default settings. Please proceed with caution as this will reset all settings to factory defaults.
Ē	Pixel Fix	Turn on the device and confirm bad pixel correction in the function settings. If correction is needed, cover the lens cap and follow the prompts to repair bad pixels. Save after correction. Use the navigation buttons to move the cursor, the power button to switch options, and briefly press the menu button to save.
	Image Calibration	Enter the image calibration menu. If calibration is required, select "Confirm", cover the lens cap, and briefly press the menu button to calibrate background image uniformity. Calibration is automatically saved upon completion.
	Auto Ba ll istics	Options: On, Off, Settings. Selecting "On" enables auto ballistics, while "Off" disables it. "Settings" allows adjustment of ballistic parameters.
i	Version	Select "Version".

7. APP Connection

Download the dedicated app on Android/iOS.



Download APP by Scanning the QR code according to the mobile phone system.



8. Technical Specifications



74.55mm

250.65mm

RA6-50LRF

Sensor:	
Туре	Uncooled Vanadium Oxide (VOx)
Resolution	640x512
Frame Rate	50 Hz
Pixel Size	12µm
NETD	≤18mk
Optics:	
Objective Lens	50mm/F1.0
Base Magnification	2.8X
Digital Zoom	1x / 2 x/ 4 x/ 8x
Exit Pupil Distance	50 mm
Diopter Adjustment	+5/-5 D
Focus Distance	5m - ∞
Field of View	8.8°X6.6°
Detection Range	2500m (Target Size: 1.7m x 0.5m)

Display:	
Color Modes	White Hot, High Contrast, Black Hot, Low Light, Fusion
Type/Resolution	0.39 inch / OLED / 1024X768
Power:	
3D Gyroscope	Yes
Power Supply	3-4.2 V
Battery	18650 Li-ion, 3500mAh
External Power	5V (USB)
Runtime	5 hours
Shock Resistance	10000 J
Waterproof Rating	IP66
Operating Temperature	-20°C~+50°C
Size	250.65x74.55x83.35mm
Weight	749g
Recorder:	
Video/Photo Resolution	1024x768
Video/Photo Format	.mp4 / .jpg
Storage Card	Built-in 32GB Memory Card
Wireless Channel:	
Frequency	2.4GHz
Standard	802.11 b/g
WiFi Range	15m
Rangefinder:	
Wavelength	905nm

Maximum Range	1000m
Accuracy	+/-1m

9. Maintenance and Care

(1) Power off the device when not in use to extend its operational life.

(2) Avoid touching the lens surface. Clean only when necessary using a dedicated lens cloth.

(3) Remove the battery during storage or transportation.

- (4) Store the device in a cool, dry environment.
- (5) Clean the exterior with a soft, dry cloth. Avoid chemical solvents.

(6) The thermal imaging Device lens should only be cleaned when visibly dirty. Avoid touching the lens surface, as the acidic substances left by fingerprints can damage the coating and lens surface. Use only a dedicated lens cloth for cleaning.

(7) Perform a power-on check and calibration every six months if the device is unused for an extended period.



Thermal Imaging & Night Vision www.falconoptic.com